

# Manual Supplement

Manual Title: 830 Users  
USB Number: 4473175  
Print Date: July 2014  
Revision/Date:

Supplement Issue: **2**  
Issue Date: 1/16  
Page Count: 3

---

---

This supplement contains information necessary to ensure the accuracy of the above manual.




### ⚠ Warning

For safe operation and maintenance of the product:

- **Repair the Product before use if the battery leaks.**
- **Be sure that the battery polarity is correct to prevent battery leakage.**
- **Use only Fluke approved power adapters to charge the battery.**

On page 19, replace **Figure 4-4**, and add the following **Caution**:



**Figure 4-4. Parts of sensor**

### ⚠ Caution

**To prevent damage to the sensor, do not drop. The sensor requires recalibration from service center if dropped. A faulty sensor significantly affects the diagnostic accuracy.**

On page 134, in the Laser section, replace Wavelength with:

Wavelength: 670 nm  $\pm$ 10 nm (red, visible)

On page 135, **Radio Frequency Emissions**, change:

From:	Particulars	IEC CISPR 11: Group 1, Class A
To:	Particulars	IEC CISPR 11: Group 1, Class B

## Change #2, 95, 541

On page 3, in the **Symbols** table, replace the CSA with:

	Certified by CSA Group to North American safety standards.
---	--

On page 135, under **Safety** replace, Electrical with:

Electrical      IEC 61010-1, Pollution Degree 2